



# Illinois Department of Transportation

2300 South Dirksen Parkway / Springfield, Illinois / 62764

To: Users of the Highway Standards

Subject: Revision #205

Date: September 14, 2004

Revision #205 of the Highway Standards, effective for the January 1, 2005 letting, is now available on the Department's website <http://www.dot.il.gov/desenv/hwystds/stdns.html>. The revisions are as follows.

<u>Removed</u>	<u>Inserted</u>	<u>Remarks</u>
Section 630 Index January 1, 2004	Section 630 Index January 1, 2005	Updated
630001-04	630001-05	Revised post in impervious material.
630101-04	630101-05	Revised Case IV on sheet 2 of 2.
630201-02	630201-03	Added holes in the stabilization for posts.
630301-02	630301-03	Corrected ground line in Section A-A.
636001	636001-01	Corrected note on post anchor detail.
Section 700 Index April 15, 2004	Section 700 Index January 1, 2005	Updated
701001	701001-01	Revised title and notes.
701006-01	701006-02	Revised title, notes, and sign spacing.
701011	701011-01	Revised title, notes, and sign spacing.
701101	701101-01	Revised title, notes, and sign spacing.
701106	701106-01	Revised title.
701201-01	701201-02	Revised title and notes. Moved flagger.
701206	701206-01	Revised title and notes.
701301-01	701301-02	Deleted FLAGGER SYMBOL sign.
701306	701306-01	Deleted FLAGGER SYMBOL sign and revised sign spacing.

## Revision #205

701316-02	701316-03	Revised notes, deleted pavement markers and advisory speed sign.
701321-07	701321-08	Revised notes, deleted pavement markers and advisory speed sign.
701326-01	701326-02	Moved flaggers off roadway and deleted FLAGGER SYMBOL sign.
701331-01	701331-02	Deleted DETOUR AHEAD sign.
701336-03	701336-04	Deleted FLAGGER SYMBOL sign and revised sign spacing.
701400-01	701400-02	Added signs for 2 lane closures.
701401-02	701401-03	Revised the first general note.
701411-02	701411-03	Revised spacing of devices.
701426-01	701426-02	Revised Detail A and deleted FLAGGER SYMBOL sign.
	701446	New Standard.
701501-02	701501-03	Deleted FLAGGER SYMBOL sign and re-positioned flaggers.
701502	701502-01	Revised notes and deleted FLAGGER SYMBOL sign.
701601-03	701601-04	Added tangent distance to 2 lane closure taper.
701602-01	701602-02	Revised notes and deleted FLAGGER SYMBOL sign.
701606-03	701606-04	Added tangent distance to 2 lane closure taper.
701701-03	701701-04	Deleted FLAGGER SYMBOL signs and re-positioned flagger.
702001-04	702001-05	Added note to work limit signing and re-added Type I barricade.
Section 800 Index January 1, 2004	Section 800 Index January 1, 2005	Updated
877001-01	877001-02	Revised size of sign panel and location of handhole.

Revision #205

877006-01	877006-02	Revised sign panel, handhole, arm angle, and table.
877011-01	877011-02	Revised sign panel, handhole, tenon top, pole height, and pole base wiring.
878001-02	878001-03	Revised Type E foundation detail.
Section BLR Index January 1, 2003	Section BLR Index January 1, 2005	Updated
BLR 10-3	BLR 10-4	Revised title and revised Type D and Type E joints.
BLR 14-7	BLR 14-8	Joint corrections and revised general notes.

Questions regarding the Highway Standards should be directed to the Policy and Procedures Section in the Bureau of Design and Environment at 217-785-0721.

Very truly yours,

Michael L. Hine  
Engineer of Design and Environment